

FIG. 1
(PRIOR ART)




FIG. 2
(PRIOR ART)






FIG. 3
(PRIOR ART)



F I G . 4



F I G . 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9

STATE	BEFORE DRYING (UPPER SURFACE)	BEFORE DRYING (CROSS SECTION)	AFTER DRYING (CROSS SECTION)
AMOUNT OF PASTE IS EXCESSIVE			
AMOUNT OF PASTE IS SUITABLE			
AMOUNT OF PASTE IS SMALL (1)			
AMOUNT OF PASTE IS SMALL (2)			
AMOUNT OF PASTE IS LACKING			
CELL IS EMPTY			

FIG. 10A




FIG. 10B




FIG. 10C




FIG. 11




FIG. 12












FIG. 13

STATE	BEFORE DRYING (UPPER SURFACE)	AFTER BINARY OPERATION (UPPER SURFACE)
AMOUNT OF PASTE IS EXCESSIVE		
AMOUNT OF PASTE IS SUITABLE		
AMOUNT OF PASTE IS SMALL (1)		
AMOUNT OF PASTE IS SMALL (2)		
AMOUNT OF PASTE IS LACKING		
CELL IS EMPTY	